30741

Material Safety Data Sheet

May be used to comply with OSHA's Hazard Communication Standard, 29 CFR 1910.1200. Standard must be consulted for specific requirements.

U.S. Department of Labor

Occupational Safety and Health Administration (Non-Mandatory Form)

Form Approved OMB No. 1218-0072



Note: Blank spaces are not permitted. If any item is not applicable, or no SATIN KLEAN POWDERED HAND SOAP information is available, the space must be marked to indicate that. Section I Emergency Telephone Number (513) 527-5500 Manufacturer's Name KUTOL PRODUCTS COMPANY Address (Number, Street, City, State, and ZIP Code) Telephone Number for Information 7650 CAMARGO ROAD (513) 527-5500 Date Prepared CINCINNATI, OHIO 45243 11/01/93 Signature of Preparer (optional) Section II — Hazardous Ingredients/Identity Information Other Limits Hazardous Components (Specific Chemical Identity; Common Name(s)) OSHA PEL **ACGIH TLV** Recommended % (optional) $0.1MG/M^3$ QUARTZ & SILICA 53% CONTAINS: QUARTZ CAS# 14808-60-7 POTASSIUM ALUMINOSILICATE CAS# 1327-44-2 SODIUM ALUMINOSILICATE CAS# 1344-00-9 Section III - Physical/Chemical Characteristics **Boiling Point** Specific Gravity (H2O = 1) 1.32 N/A Vapor Pressure (mm Hg.) Melting Point N/A N/A Vapor Density (AIR = 1) **Evaporation Rate** < 1 N/A (Butyl Acetate - 1) Solubility in Water 228 Appearance and Odor FINE PINK POWDER, BLAND SCENT Section IV — Fire and Explosion Hazard Data UEL Flash Point (Method Used) Flammable Limits N/A N/A N/A N/A Extinguishing Media ANY - WILL NOT SUPPORT COMBUSTION Special Fire Fighting Procedures NONE Unusual Fire and Explosion Hazards NONE

tability	Unstable		Conditions to Avoid	NO	NE		-
	Stable	х					
compatibility (A	Materials to Avoid)	<u> </u>		NO	NE		
zardous Decom	position or Byprodu	cts		NO	NE		
azardous	May Occur	1	Conditions to Avoid	NO			
olymerization	Will Not Occur	x		NO	NE-		
ection VI -	Health Hazard						<u></u>
oute(s) of Entry:		lation?	N/A	Skin?	N/A	Ingestion? N/A	
ealth Hazards (A	Acute and Chronic)		NONE KN	OWN		M/ R	
							
arcinogenicity:	NO NTF	>?	NO	IARC Mor	ographs? NO	OSHA Regulated?	NO
· .							
igns and Sympt	oms of Exposure		NONE KN	OWN			
ledical Condition	ns rated by Exposure		NO MEDI	CAL COND	ITIONS AR	E KNOWN TO BE AGO	GRAVATED
, , , , , , , , , , , , , , , , , , ,	did by Exposit	E	BY EXPOSURE	TO THIS	PRODUCT.		
mergency and	First Aid Procedures						
· INGESTED	CONSTITUTA D	PHYST	CTAN CONTAINS	SOAP VOM	TTTNG AND/C	R SLIGHT RISE IN BOD	Y TEMPERAT
	-					OR SLIGHT RISE IN BOD	
Y OCCUR.F	LUSH EYES WI	TH A	COPIUS AMOUNT	OF WATER		OR SLIGHT RISE IN BOD B EYES-CONTAINS INSOL	
AY OCCUR.F.	LUSH EYES WI	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled	OF WATER	.DO NOT RUE	B EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F	LUSH EYES WI - Precautions	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled	OF WATER	.DO NOT RUE		UBLE SCRUE
Y OCCUR.F	LUSH EYES WI - Precautions	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled	OF WATER	.DO NOT RUE	B EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take	LUSH EYES WI — Precautions (en in Case Material	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled SY	OF WATER Jse WEEP UP (DO NOT RUE	EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take	LUSH EYES WI — Precautions (en in Case Material	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled SY	OF WATER Jse WEEP UP (DO NOT RUE	B EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take	LUSH EYES WI — Precautions (en in Case Material	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT	OF WATER JSE WEEP UP (DO NOT RUE OR SHOVEL	EYES-CONTAINS INSOL	UBLE SCRUE
Section VII - Steps to Be Take	LUSH EYES WI Precautions (en in Case Material Method	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT	OF WATER JSE WEEP UP (DO NOT RUE OR SHOVEL	EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take Vaste Disposal	LUSH EYES WI Precautions 1 en in Case Material Method Taken in Handling	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT Storing FOR BE	OF WATER JSE WEEP UP (DO NOT RUE OR SHOVEL	EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take Vaste Disposal	LUSH EYES WI Precautions 1 en in Case Material Method Taken in Handling	TH A	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT	OF WATER JSE WEEP UP (DO NOT RUE OR SHOVEL	EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take Vaste Disposal	LUSH EYES WI Precautions (en in Case Material Method Taken in Handling	In A lor Sa Is Rele	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT Storing FOR BE NONE	OF WATER JSE WEEP UP (DO NOT RUE OR SHOVEL	EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take Vaste Disposal in Precautions to Be Other Precaution Section VIII	LUSH EYES WI Precautions (en in Case Material Method Taken in Handling Taken in Handling	TH A for Sa is Rele If g and S	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT Storing FOR BE NONE	OF WATER JSE WEEP UP (DO NOT RUE OR SHOVEL	EYES-CONTAINS INSOL	UBLE SCRUE
Y OCCUR.F. Section VII - Iteps to Be Take Vaste Disposal in Precautions to Be Other Precaution Section VIII Respiratory Protein	LUSH EYES WI Precautions (en in Case Material Method Taken in Handling Taken in Handling Control Mea	TH A for Sa is Rele If g and S	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT Storing FOR BE NONE	OF WATER JSE WEEP UP (DO NOT RUE DR SHOVEL LOCAL, ST	INTO LEAKPROOF C	UBLE SCRUE
Section VII - Diteps to Be Take Vaste Disposal in Precautions to Be Other Precaution Section VIII Respiratory Protes	LUSH EYES WI Precautions of the process of the proc	In the state of th	COPIUS AMOUNT fe Handling and I ased or Spilled ST ANDFILL WIT NONE NONE NONE	OF WATER JSE WEEP UP (DO NOT RUE DR SHOVEL LOCAL, ST TS, STORE	EYES-CONTAINS INSOL	UBLE SCRUE
Section VII - Steps to Be Take Waste Disposal in Precautions to Be Other Precaution Section VIII Respiratory Prot	LUSH EYES WI Precautions (en in Case Material Method Taken in Handling Taken in Handling Control Mea ection (Specify Type Local Exhaust Mechanical (Gene	In the state of th	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT Storing FOR BE NONE	OF WATER Jse WEEP UP (DO NOT RUE DR SHOVEL LOCAL, ST TS, STORE Special Other	INTO LEAKPROOF C	UBLE SCRUE
AY OCCUR.F. Section VII - Steps to Be Take Waste Disposal in Precautions to B Other Precaution Section VIII	LUSH EYES WI Precautions (en in Case Material Method Taken in Handling Taken in Handling Control Mea ection (Specify Type Local Exhaust Mechanical (Gene	In the state of th	COPIUS AMOUNT fe Handling and I ased or Spilled ST ANDFILL WIT NONE NONE NONE	OF WATER Jse WEEP UP (DO NOT RUE DR SHOVEL LOCAL, ST TS, STORE	INTO LEAKPROOF C CATE AND FEDERAL I E IN A DRY AREA.	UBLE SCRUE
Naste Disposal Section VIII - Steps to Be Take Precautions to Be Disposal Section VIII - Respiratory Protective Glove	LUSH EYES WI Precautions (en in Case Material Method Taken in Handling Taken in Handling Control Mea ection (Specify Type Local Exhaust Mechanical (Gene	In A state of the	COPIUS AMOUNT fe Handling and I ased or Spilled SI ANDFILL WIT NONE NONE NONE NONE	OF WATER Jse WEEP UP (DO NOT RUE DR SHOVEL LOCAL, ST TS, STORE Special Other	INTO LEAKPROOF C CATE AND FEDERAL I IN A DRY AREA. NONE	UBLE SCRUE